

GreenMotion Auction

B2B VEHICLE INSPECTION REPORT

Report #INS-2026-0421 · Sample (anonymised)

2023 Polestar 2 Long Range Dual Motor

Inspected 2026-05-12 · Hamburg, DE (partner facility)

142-point checklist · 38 photographs · OEM SoH where exposed
For professional vehicle dealers only

Executive summary

Report ID	INS-2026-0421	Lot	PSL2-23-001
Vehicle	2023 Polestar 2 Long Range Dual Motor	VIN (masked)	YSMZZZAAZRB*****
Mileage	42,180 km	First registration	2023-04-18
Inspected	2026-05-12	Inspector ref.	GMA-DE-0142
Location	Hamburg, DE (partner facility)	Photos	38
Battery SoH	87% (OEM OBD (Polestar diagnostic API))	WLTP range	540 km
VAT scheme	VAT-qualifying (intra-EU)	Points checked	142

Category	Points	Result
Total inspected	142	Approved for listing
Pass	140	—
Attention (documented)	2	Wheel cosmetic · noted on p.7
Fail	0	—
Road test	18 km	Completed

Overall grading: Grade A — suitable for B2B auction subject to buyer's own market due diligence. This report supplements, not replaces, buyer inspection rights under the GreenMotion Buyer Agreement.

A. Vehicle identity & documentation — 18 points · Result: Pass

- VIN plate & windscreen label match (masked in sample)
- Registration certificate copy on file
- Service history — Polestar digital records complete
- Keys: 2× key card + 1× physical key
- No export block or finance encumbrance flagged

B. Exterior & structural — 32 points · Result: Pass (1 note)

- Panel gaps within OEM tolerance all corners
- Paint depth map — no secondary-structure repair
- Windscreen & glass — no chips >5mm
- ■ Front-left alloy wheel — kerb scuff ~2cm (photo 07)
- Lights, sensors, charging flap — functional

C. Interior & cabin — 24 points · Result: Pass

- Seat wear consistent with 42k km
- Infotainment — software v3.2.1, no fault codes
- Odour-free cabin, no moisture under mats
- ISOFIX points accessible
- All window regulators tested

D. Mechanical & road test — 28 points · Result: Pass

- Brake discs/pads — front 6mm / rear 7mm remaining
- Tyres — Michelin Pilot Sport 4, 5.2mm min tread
- Suspension — no play, no leaks
- Road test 18 km — no drivetrain vibration
- Regenerative braking levels 1–3 operational

E. High-voltage & battery (BEV) — 22 points · Result: Pass

- SoH 87% via OEM OBD (method stated, not synthesised)
- HV battery enclosure — no impact markers
- Charging test AC Type 2 + DC CCS — OK
- No isolation fault codes (U0100 family clear)
- Charging history consistent with mileage

F. ADAS & calibration — 12 points · Result: Pass

- Front radar & camera cluster — no fault codes
- ADAS calibration log dated 2026-03-01
- Parking sensors 360° — responsive

G. Commercial disclosure (B2B) — 6 points · Result: Pass

- Margin / VAT scheme declared on listing
- Known options list matches equipment observed
- Auction reference PSL2-23-001 linked

Appendix — 142-point checklist (condensed)

Each line is a discrete inspection point recorded as Pass unless noted in sections A–G.

Pt	Check item	Result
1	A.01 Vehicle identity & documentation — checkpoint 1	Pass
2	A.02 Vehicle identity & documentation — checkpoint 2	Pass
3	A.03 Vehicle identity & documentation — checkpoint 3	Pass
4	A.04 Vehicle identity & documentation — checkpoint 4	Pass
5	A.05 Vehicle identity & documentation — checkpoint 5	Pass
6	A.06 Vehicle identity & documentation — checkpoint 6	Pass
7	A.07 Vehicle identity & documentation — checkpoint 7	Pass
8	A.08 Vehicle identity & documentation — checkpoint 8	Pass
9	A.09 Vehicle identity & documentation — checkpoint 9	Pass
10	A.10 Vehicle identity & documentation — checkpoint 10	Pass
11	A.11 Vehicle identity & documentation — checkpoint 11	Pass
12	A.12 Vehicle identity & documentation — checkpoint 12	Pass
13	A.13 Vehicle identity & documentation — checkpoint 13	Pass
14	A.14 Vehicle identity & documentation — checkpoint 14	Pass
15	A.15 Vehicle identity & documentation — checkpoint 15	Pass
16	A.16 Vehicle identity & documentation — checkpoint 16	Pass
17	A.17 Vehicle identity & documentation — checkpoint 17	Pass
18	A.18 Vehicle identity & documentation — checkpoint 18	Pass
19	B.01 Exterior & structural — checkpoint 1	Pass
20	B.02 Exterior & structural — checkpoint 2	Pass
21	B.03 Exterior & structural — checkpoint 3	Pass
22	B.04 Exterior & structural — checkpoint 4	Pass
23	B.05 Exterior & structural — checkpoint 5	Pass
24	B.06 Exterior & structural — checkpoint 6	Pass
25	B.07 Exterior & structural — checkpoint 7	Pass
26	B.08 Exterior & structural — checkpoint 8	Pass
27	B.09 Exterior & structural — checkpoint 9	Pass
28	B.10 Exterior & structural — checkpoint 10	Pass
29	B.11 Exterior & structural — checkpoint 11	Pass
30	B.12 Exterior & structural — checkpoint 12	Pass
31	B.13 Exterior & structural — checkpoint 13	Pass
32	B.14 Exterior & structural — checkpoint 14	Pass
33	B.15 Exterior & structural — checkpoint 15	Pass
34	B.16 Exterior & structural — checkpoint 16	Pass
35	B.17 Exterior & structural — checkpoint 17	Pass
36	B.18 Exterior & structural — checkpoint 18	Pass
37	B.19 Exterior & structural — checkpoint 19	Pass
38	B.20 Exterior & structural — checkpoint 20	Pass

39	B.21 Exterior & structural — checkpoint 21	Pass
40	B.22 Exterior & structural — checkpoint 22	Pass
41	B.23 Exterior & structural — checkpoint 23	Pass
42	B.24 Exterior & structural — checkpoint 24	Pass
43	B.25 Exterior & structural — checkpoint 25	Pass
44	B.26 Exterior & structural — checkpoint 26	Pass
45	B.27 Exterior & structural — checkpoint 27	Pass
46	B.28 Exterior & structural — checkpoint 28	Pass
47	B.29 Exterior & structural — checkpoint 29	Pass
48	B.30 Exterior & structural — checkpoint 30	Pass
49	B.31 Exterior & structural — checkpoint 31	Pass
50	B.32 Exterior & structural — checkpoint 32	Pass
51	C.01 Interior & cabin — checkpoint 1	Pass
52	C.02 Interior & cabin — checkpoint 2	Pass
53	C.03 Interior & cabin — checkpoint 3	Pass
54	C.04 Interior & cabin — checkpoint 4	Pass
55	C.05 Interior & cabin — checkpoint 5	Pass
56	C.06 Interior & cabin — checkpoint 6	Pass
57	C.07 Interior & cabin — checkpoint 7	Pass
58	C.08 Interior & cabin — checkpoint 8	Pass
59	C.09 Interior & cabin — checkpoint 9	Pass
60	C.10 Interior & cabin — checkpoint 10	Pass
61	C.11 Interior & cabin — checkpoint 11	Pass
62	C.12 Interior & cabin — checkpoint 12	Pass
63	C.13 Interior & cabin — checkpoint 13	Pass
64	C.14 Interior & cabin — checkpoint 14	Pass
65	C.15 Interior & cabin — checkpoint 15	Pass
66	C.16 Interior & cabin — checkpoint 16	Pass
67	C.17 Interior & cabin — checkpoint 17	Pass
68	C.18 Interior & cabin — checkpoint 18	Pass
69	C.19 Interior & cabin — checkpoint 19	Pass
70	C.20 Interior & cabin — checkpoint 20	Pass
71	C.21 Interior & cabin — checkpoint 21	Pass
72	C.22 Interior & cabin — checkpoint 22	Pass
73	C.23 Interior & cabin — checkpoint 23	Pass
74	C.24 Interior & cabin — checkpoint 24	Pass
75	D.01 Mechanical & road test — checkpoint 1	Pass
76	D.02 Mechanical & road test — checkpoint 2	Pass
77	D.03 Mechanical & road test — checkpoint 3	Pass
78	D.04 Mechanical & road test — checkpoint 4	Pass
79	D.05 Mechanical & road test — checkpoint 5	Pass

80	D.06 Mechanical & road test — checkpoint 6	Pass
81	D.07 Mechanical & road test — checkpoint 7	Pass
82	D.08 Mechanical & road test — checkpoint 8	Pass
83	D.09 Mechanical & road test — checkpoint 9	Pass
84	D.10 Mechanical & road test — checkpoint 10	Pass
85	D.11 Mechanical & road test — checkpoint 11	Pass
86	D.12 Mechanical & road test — checkpoint 12	Pass
87	D.13 Mechanical & road test — checkpoint 13	Pass
88	D.14 Mechanical & road test — checkpoint 14	Pass
89	D.15 Mechanical & road test — checkpoint 15	Pass
90	D.16 Mechanical & road test — checkpoint 16	Pass
91	D.17 Mechanical & road test — checkpoint 17	Pass
92	D.18 Mechanical & road test — checkpoint 18	Pass
93	D.19 Mechanical & road test — checkpoint 19	Pass
94	D.20 Mechanical & road test — checkpoint 20	Pass
95	D.21 Mechanical & road test — checkpoint 21	Pass
96	D.22 Mechanical & road test — checkpoint 22	Pass
97	D.23 Mechanical & road test — checkpoint 23	Pass
98	D.24 Mechanical & road test — checkpoint 24	Pass
99	D.25 Mechanical & road test — checkpoint 25	Pass
100	D.26 Mechanical & road test — checkpoint 26	Pass
101	D.27 Mechanical & road test — checkpoint 27	Pass
102	D.28 Mechanical & road test — checkpoint 28	Pass
103	E.01 High-voltage & battery (BEV) — checkpoint 1	Pass
104	E.02 High-voltage & battery (BEV) — checkpoint 2	Pass
105	E.03 High-voltage & battery (BEV) — checkpoint 3	Pass
106	E.04 High-voltage & battery (BEV) — checkpoint 4	Pass
107	E.05 High-voltage & battery (BEV) — checkpoint 5	Pass
108	E.06 High-voltage & battery (BEV) — checkpoint 6	Pass
109	E.07 High-voltage & battery (BEV) — checkpoint 7	Pass
110	E.08 High-voltage & battery (BEV) — checkpoint 8	Pass
111	E.09 High-voltage & battery (BEV) — checkpoint 9	Pass
112	E.10 High-voltage & battery (BEV) — checkpoint 10	Pass
113	E.11 High-voltage & battery (BEV) — checkpoint 11	Pass
114	E.12 High-voltage & battery (BEV) — checkpoint 12	Pass
115	E.13 High-voltage & battery (BEV) — checkpoint 13	Pass
116	E.14 High-voltage & battery (BEV) — checkpoint 14	Pass
117	E.15 High-voltage & battery (BEV) — checkpoint 15	Pass
118	E.16 High-voltage & battery (BEV) — checkpoint 16	Pass
119	E.17 High-voltage & battery (BEV) — checkpoint 17	Pass
120	E.18 High-voltage & battery (BEV) — checkpoint 18	Pass

121	E.19 High-voltage & battery (BEV) — checkpoint 19	Pass
122	E.20 High-voltage & battery (BEV) — checkpoint 20	Pass
123	E.21 High-voltage & battery (BEV) — checkpoint 21	Pass
124	E.22 High-voltage & battery (BEV) — checkpoint 22	Pass
125	F.01 ADAS & calibration — checkpoint 1	Pass
126	F.02 ADAS & calibration — checkpoint 2	Pass
127	F.03 ADAS & calibration — checkpoint 3	Pass
128	F.04 ADAS & calibration — checkpoint 4	Pass
129	F.05 ADAS & calibration — checkpoint 5	Pass
130	F.06 ADAS & calibration — checkpoint 6	Pass
131	F.07 ADAS & calibration — checkpoint 7	Pass
132	F.08 ADAS & calibration — checkpoint 8	Pass
133	F.09 ADAS & calibration — checkpoint 9	Pass
134	F.10 ADAS & calibration — checkpoint 10	Pass
135	F.11 ADAS & calibration — checkpoint 11	Pass
136	F.12 ADAS & calibration — checkpoint 12	Pass
137	G.01 Commercial disclosure (B2B) — checkpoint 1	Pass
138	G.02 Commercial disclosure (B2B) — checkpoint 2	Pass
139	G.03 Commercial disclosure (B2B) — checkpoint 3	Pass
140	G.04 Commercial disclosure (B2B) — checkpoint 4	Pass
141	G.05 Commercial disclosure (B2B) — checkpoint 5	Pass
142	G.06 Commercial disclosure (B2B) — checkpoint 6	Pass

Photo index (excerpt)

#	Description	Category
01	Front 3/4 — daylight	Exterior
04	VIN area (masked in sample)	Identity
07	Front-left alloy — kerb scuff	Exterior
12	Dashboard + mileage	Interior
18	OBD SoH screenshot	HV / Battery
24	Underbody — no fluid leaks	Mechanical
31	Charging port Type 2	HV / Battery
38	Rear 3/4 — daylight	Exterior

This is an anonymised sample of the inspection report format issued by GreenMotion Auction (operator: GreenMotion Solutions Kft., EU VAT HU32579570) before bidding on lot PSL2-23-001. It is not a warranty, export certificate, or type-approval document. Battery State of Health is shown only where the OEM exposes a reading via OBD — we do not publish synthetic SoH figures. Buyers must verify VAT treatment, import duties, and registration requirements for their market. Disputes: notify within 5 working days of delivery with photos; remedy per Buyer Agreement.